






JOEL








		
1	1X	1/1
2	1X	1/1
3	3X	1/1
4	1X	1/1
5	1X	1/1
6	1X	1/1
7	3X	1/1
8	1X	1/1


1/1

A	M6X14	B	Ø20	C	5MM	D	Ø16		
									
24x		10x		1x		9x			


I.

1



A	M6x14
	12x
C	5MM
	1x
D	Ø16
	4x
100%	



2





A	M6x14
	12x
C	5MM
	1x
D	Ø16
	5x
100%	

II.

3




4





5




B






Ø20

6x



6



LE TRI
+ FACILE



Séparez les éléments avant de trier